ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

## BBMP ENGINEERING DEPARTMENT

### Road History Data Sheet

### General

| Zone | Ward No. | Ward Name |
|---|---|---|
| YELAHANKA | 2 | Chowdeshwari Ward |
| **Street ID** | **Street Name** | **Significant Landmark** |
| W0011, W0020, W0022, W0017, W0013, W0007 | NA | surya vamshi layout |
| **Segment No.** | **Total Length (m)** | |
| 2/C-W0011/S125929 | 229.36 | |

**Segment Details**

| Seg No. | Length (m) | Start Coordinates | | End Coordinates | | From | To |
|---|---|---|---|---|---|---|---|
| 1 | 51.05 | 77.571811 | 13.131365 | 77.571703 | 13.130916 | W0020 | DEAD END |
| 2 | 50.07 | 77.571408 | 13.131444 | 77.571306 | 13.131002 | W0020 | DEAD END |
| 3 | 63.62 | 77.572283 | 13.131352 | 77.572409 | 13.131914 | W0020 | DEAD END |
| 4 | 64.62 | 77.571896 | 13.131425 | 77.572017 | 13.131998 | W0020 | DEAD END |

### Work Details

**History of Road / Lane / Circles**

| Name of the Work | Sanctioned Estimated Amount (Rs.) | Sanctioned Year |
|---|---|---|
| Improvements to roads and drain at surya vamshi layout in Ward no 02 of Yelahanka Sub-Division Yelahanka zone | 2000000 | 2017 |
| **Year** | **Type of Work** | **Other Work Type** |
| 2017 - 2018 | Others | DRAIN |
| **Tender** | **Work Details** | **Job No. / Work Code** |
| Tender | Improvements to roads and drain at surya vamshi layout in Ward no 02 of Yelahanka Sub-Division Yelahanka zone | 002-17-000031 |
| **Work Order No.** | **Work Order Date** | **Period of Extention** |
| EE (YNK.D) E-PMT /WO/32/2017 -18 | 02/05/2017 | 90 DAYS |
| **Defect Liability Period From** | **Defect Liability Period To** | **Multiple road involved with the same Job No/ Work Code #** |
| 30/06/2017 | 29/06/2018 | Yes |

### Contractor Details

| Name of Contractor | Contractor Reg No (BBMP/PWD) | Expenditure Booked \ Released (Rs) |
|---|---|---|
| G.VENKATEGOWDA | | 0.00 |
| **Phone No.** | **E-Mail ID** | |



Asst. Executive Engineer
Yelahanka Sub. Divison
(BBMP Ynk. Zn)
Yelahanka, Bangalore

45507797

## Field Inspection Details

| Number of Trees | Any Other Information | Name |
|---|---|---|
| 12 | | PAVANA NAGATHI |
| **Date of Inspection** | **Remarks** | |
| 29/07/2017 | COMPLETED | |

| Category | Image | Photo Remark |
|---|---|---|
| Drain Condition | | This photo seems out of range. |
| Drain Condition | | This photo seems out of range. |
| Drain Condition | | This photo seems out of range. |
| Drain Condition | | This photo seems out of range. |
| Drain Condition | | This photo seems out of range. |
| Drain Condition | | This photo seems out of range. |
| Drain Condition | | This photo seems out of range. |
| Drain Condition | | This photo seems out of range. |
| Drain Condition | | This photo seems out of range. |

**Zone:** YELAHANKA **Ward No:** 2 **Ward Name:** Chowdeshwari Ward **Street ID:** W0011, W0020, W0022, W0017,

Asst. Executive Engineer
Yelahanka Sub. Divison
(BBMP Ynk. Zn)
Yelahanka, Bangalore

| | | |
|---|---|---|
| Drain Condition | | This photo seems out of range. |
| Drain Condition | | This photo seems out of range. |

**Remarks**

| Designation | Approver Name | Date | Target Date | Remark |
|---|---|---|---|---|
| CE | VASU K M | 29/07/2017 | 28/08/2017 | COMPLETED |
| SE | VASU K M | 29/07/2017 | 28/08/2017 | COMPLETED |
| EE | VASU K M | 29/07/2017 | 28/08/2017 | COMPLETED |
| AEE | DEVARAJ | 29/07/2017 | 28/08/2017 | COMPLETED |
| AE | PAVANA NAGATHI | 29/07/2017 | 28/08/2017 | COMPLETED |
| AE | PAVANA NAGATHI | 29/07/2017 | 28/08/2017 | COMPLETED |

Asst. Executive Engineer
Yelahanka Sub. Divison
(BBMP Ynk. Zn)
Yelahanka, Bangalore

**Zone:** YELAHANKA **Ward No:** 2 **Ward Name:** Chowdeshwari Ward **Street ID:** W0011, W0020, W0022, W0017,